

Wismer & Rawlings Electric Ltd	Serial#: NAME PLATE MISSING 20240813	Mfr:	Control#: 7769746
#118-1647 BROADWAY ST.	Location: VERUS UTILITY- CAMPBELL RIVER B	kV:	Order#: 730362
PORT COQUITLAM, BC V3C 6P8 CA	Equipment: TRANSFORMER	kVA:	Account: 6066
ATTN: RACHEL KENT	Compartment: MAIN(BOTTOM)	Year Mf'd:	Received: 08/26/2024
PO#: 29596	Breathing:	Syringe ID:	Reported: 09/03/2024
Project ID: VERUS UTILITY	Bank: Phase:	Bottle ID:	
Customer ID:	Fluid: MIN	Sampled By:	

	Lab Control Number:	7769746
	Date Sampled:	08/13/2024
	Order Number:	730362
	Oil Temp:	
PCB	Concentration (mg/kg):	< 1.0 mg/kg
ASTM Method D-4059¹	PCB Type (Arocolor):	ND
	Reporting Limit:	1
Comment:		

End of Test Report

AVO DIAGNOSTIC SERVICES
110, 7304 30TH STREET S.E. + CALGARY, AB + T2C 1W2
403 203 0550 + 403 863 2258
WWW.AVODIAGNOSTICS.COM

Authorized By: 
ROBERT BELFROY
SUPERVISING CHEMIST

Notations: 1. Analysis is ISO/IEC 17025:2017 accredited, ANAB Accredited Certificate Number L2303.01 2. This test is conducted by a subcontracted laboratory. 3. Subcontracted laboratory has received ISO Standard 17025 accreditation for this test. 5. This test is conducted by AVO Diagnostic Services Laboratory other than Primary Lab. 6. AVO Diagnostic Services Laboratory has received ISO Standard 17025 accreditation for this test. 7. Imported Sample: AVO Diagnostic Services accepts no responsibility for these results; accreditation status does not apply to these results. 8. Imported Equipment 10. mg/kg, µg/g, µg/mL, µL/L = ppm, µg/L = ppb, mN/m = dynes/cm, mm²/s = cSt

Accreditation applies to current analysis only. The analyses, opinions or interpretations contained in this report are based upon material and information supplied by the client. AVO Diagnostic Services does not imply that the contents of the sample received by this laboratory are the same as all such material in the environment from which the sample was taken. Our test results relate only to the sample or samples tested. Any interpretations or opinions expressed represent the best judgment of AVO Diagnostic Services. AVO Diagnostic Services assumes no responsibility and makes no warranty or representation, expressed or implied as to the condition, productivity or proper operation of any equipment or other property for which this report may be used or relied upon for any reason whatsoever. This test report shall not be reproduced except in full, without written approval of the laboratory.

Wismer & Rawlings Electric Ltd
 #118-1647 BROADWAY ST.

PORT COQUITLAM, BC V3C 6P8 CA
 ATTN: RACHEL KENT
 PO#: 29596

Project ID: VERUS UTILITY
Customer ID:

Serial#: 145P677H01
Location: VERUS UTILITY-
 CAMPBELL RIVER B
Equipment: TRANSFORMER
Compartment: MAIN(BOTTOM)
Breathing:
Bank: Phase:
Fluid: MIN

Mfr: WESTINGHOUSE
kV:
kVA:
Year Mf'd: 1972
Syringe ID:
Bottle ID:
Sampled By:

Control#: 7769747
Order#: 730362
Account: 6066
Received: 08/26/2024
Reported: 09/03/2024

	Lab Control Number:	7769747
	Date Sampled:	08/13/2024
	Order Number:	730362
	Oil Temp:	
PCB	Concentration (mg/kg):	< 1.0 mg/kg
ASTM Method D-4059¹	PCB Type (Arocolor):	ND
	Reporting Limit:	1
Comment:		

End of Test Report

AVO DIAGNOSTIC SERVICES
 110, 7304 30TH STREET S.E. + CALGARY, AB + T2C 1W2
 403 203 0550 + 403 863 2258
 WWW.AVODIAGNOSTICS.COM

Authorized By: 
 ROBERT BELFROY
 SUPERVISING CHEMIST

Notations: 1. Analysis is ISO/IEC 17025:2017 accredited, ANAB Accredited Certificate Number L2303.01 2. This test is conducted by a subcontracted laboratory. 3. Subcontracted laboratory has received ISO Standard 17025 accreditation for this test. 5. This test is conducted by AVO Diagnostic Services Laboratory other than Primary Lab. 6. AVO Diagnostic Services Laboratory has received ISO Standard 17025 accreditation for this test. 7. Imported Sample: AVO Diagnostic Services accepts no responsibility for these results; accreditation status does not apply to these results. 8. Imported Equipment 10. mg/kg, µg/g, µg/mL, µL/L = ppm, µg/L = ppb, mN/m = dynes/cm, mm²/s = cSt

Accreditation applies to current analysis only. The analyses, opinions or interpretations contained in this report are based upon material and information supplied by the client. AVO Diagnostic Services does not imply that the contents of the sample received by this laboratory are the same as all such material in the environment from which the sample was taken. Our test results relate only to the sample or samples tested. Any interpretations or opinions expressed represent the best judgment of AVO Diagnostic Services. AVO Diagnostic Services assumes no responsibility and makes no warranty or representation, expressed or implied as to the condition, productivity or proper operation of any equipment or other property for which this report may be used or relied upon for any reason whatsoever. This test report shall not be reproduced except in full, without written approval of the laboratory.

Wismer & Rawlings Electric Ltd
 #118-1647 BROADWAY ST.

PORT COQUITLAM, BC V3C 6P8 CA
 ATTN: RACHEL KENT
 PO#: 29596

Project ID: VERUS UTILITY
Customer ID:

Serial#: 145P672H01
Location: VERUS UTILITY-
 CAMPBELL RIVER B
Equipment: TRANSFORMER
Compartment: MAIN(BOTTOM)
Breathing:
Bank: Phase:
Fluid: MIN

Mfr: WESTINGHOUSE
kV:
kVA:
Year Mf'd: 1972
Syringe ID:
Bottle ID:
Sampled By:

Control#: 7769748
Order#: 730362
Account: 6066
Received: 08/26/2024
Reported: 09/03/2024

	Lab Control Number:	7769748
	Date Sampled:	08/13/2024
	Order Number:	730362
	Oil Temp:	
PCB	Concentration (mg/kg):	< 1.0 mg/kg
ASTM Method D-4059¹	PCB Type (Arocolor):	ND
	Reporting Limit:	1
Comment:		

End of Test Report

AVO DIAGNOSTIC SERVICES
 110, 7304 30TH STREET S.E. + CALGARY, AB + T2C 1W2
 403 203 0550 + 403 863 2258
 WWW.AVODIAGNOSTICS.COM

Authorized By: 
 ROBERT BELFROY
 SUPERVISING CHEMIST

Notations: 1. Analysis is ISO/IEC 17025:2017 accredited, ANAB Accredited Certificate Number L2303.01 2. This test is conducted by a subcontracted laboratory. 3. Subcontracted laboratory has received ISO Standard 17025 accreditation for this test. 5. This test is conducted by AVO Diagnostic Services Laboratory other than Primary Lab. 6. AVO Diagnostic Services Laboratory has received ISO Standard 17025 accreditation for this test. 7. Imported Sample: AVO Diagnostic Services accepts no responsibility for these results; accreditation status does not apply to these results. 8. Imported Equipment 10. mg/kg, µg/g, µg/mL, µL/L = ppm, µg/L = ppb, mN/m = dynes/cm, mm²/s = cSt

Accreditation applies to current analysis only. The analyses, opinions or interpretations contained in this report are based upon material and information supplied by the client. AVO Diagnostic Services does not imply that the contents of the sample received by this laboratory are the same as all such material in the environment from which the sample was taken. Our test results relate only to the sample or samples tested. Any interpretations or opinions expressed represent the best judgment of AVO Diagnostic Services. AVO Diagnostic Services assumes no responsibility and makes no warranty or representation, expressed or implied as to the condition, productivity or proper operation of any equipment or other property for which this report may be used or relied upon for any reason whatsoever. This test report shall not be reproduced except in full, without written approval of the laboratory.